

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
NY,
60-OSS,
1-

209-217 Main Street (Main Street Crescent)
Ossining
Westchester County
New York

HABS NY-5704

Documentation: 14 exterior photos (1979)
17 interior photos (1979)
1 photocopy of old post card
8 data pages (1982)

Samuel Dickstein, photographer, November 5, 1979

- NY-5704-1 General view of the Crescent (left side), looking north (HABS NY,60-OSS,1-1)
- NY-5704-2 General view of the Crescent (right side), looking south (HABS NY,60-OSS,1-2)
- NY-5704-3 General view of the Crescent, closer, looking southwest (HABS NY,60-OSS,1-3)
- NY-5704-4 General view of 209-217 Main Street buildings, looking northwest (HABS NY,60-OSS,1-4)
- NY-5704-5 General view of 209-211 Main Street, from east (HABS NY,60-OSS,1-A-1)
- NY-5704-6 General view of rear elevation of 209-211 Main Street, from west (HABS NY,60-OSS,1-A-2)
- NY-5704-7 Detail view of window and cornice ornamentation of 209-211 Main Street (HABS NY,60-OSS,1-A-3)
- NY-5704-8 Third floor apartment, kitchen, 209-211 Main Street (HABS NY,60-OSS,1-A-4)
- NY-5704-9 Third floor apartment, bedroom, 209-211 Main Street (HABS NY,60-OSS,1-A-5)
- NY-5704-10 Detail view of cast-iron column with acanthus leaf capital, second floor, 209-211 Main Street (HABS NY,60-OSS,1-A-6)
- NY-5704-11 Detail view of stamped metal ceiling, rear section of ground floor, 209-211 Main Street (HABS NY,60-OSS,1-A-7)
- NY-5704-12 General view of 213-215 Main Street, from east (HABS NY,60-OSS,1-B-1)
- NY-5704-13 General view of rear elevation of 213-215 Main Street, from west (HABS NY,60-OSS,1-B-2)
- NY-5704-14 Detail view of window and cornice ornamentation of 213-215 Main Street (HABS NY,60-OSS,1-B-3)
- NY-5704-15 Second floor apartment, living room, 213-215 Main Street. Note cornice and ceiling trim (HABS NY,60-OSS,1-B-4)
- NY-5704-16 Detail view of window, second floor apartment, living room, 213-215 Main Street (HABS NY,60-OSS,1-B-5)

209-217 MAIN STREET
(MAIN STREET CRESCENT)
HABS NO. NY-5704 (Pg. 2)

- NY-5704-17 Detail view of stamped metal ceiling, ground floor restaurant, 215 Mains Street (HABS NY,60-OSS,1-B-6)
- NY-5704-18 Detail view of ceiling fixture, second floor, 213-215 Main Street (HABS NY,60-OSS,1-B-7)
- NY-5704-19 Detail view of ceiling fixture, second floor, 213-215 Main Street (HABS NY,60-OSS,1-B-8)
- NY-5704-20 Detail view of second floor stairway, 213-215 Main Street (HABS NY,60-OSS,1-B-9)
- NY-5704-21 Detail view of original door and trim, third floor, 213-215 Main Street (HABS NY,60-OSS,1-B-10)
- NY-5704-22 General view of 217 Main Street, from east (HABS NY,60-OSS,1-C-1)
- NY-5704-23 View of front (east) and side (north) elevations of 217 Main Street (HABS NY,60-OSS,1-C-2)
- NY-5704-24 General view of rear elevation of 217 Main Street (HABS NY,60-OSS,1-C-3)
- NY-5704-25 Detail view of window and cornice ornamentation of 217 Main Street (HABS NY,60-OSS,1-C-4)
- NY-5704-26 Second floor apartment, living room, 217 Main Street (HABS NY,60-OSS,1-C-5)
- NY-5704-27 Detail view of window in living room, second floor apartment of 217 Main Street (HABS NY,60-OSS,1-C-6)
- NY-5704-28 Arched entrance leading to sidewalk located at front wall of basement, 217 Main Street (HABS NY,60-OSS,1-C-7)
- NY-5704-29 Detail view of cast-iron column with acanthus leaf capital, rear section of basement of 217 Main Street (HABS NY,60-OSS,1-C-8)
- NY-5704-30 Detail view of cast-iron column with acanthus leaf capital, rear section of basement of 217 Main Street (HABS NY,60-OSS,1-C-9)
- NY-5704-31 Identification plate, cast-iron facade element, 217 Main Street (HABS NY,60-OSS,1-C-10)

PHOTOCOPY:

- NY-5704-32 Photocopy of ca. 1908 postcard showing the Main Street Crescent (on left side) (HABS NY,60-OSS,1-5)